



September 12, 2023

Project Number: 222-141

Mr. Colin Lynch
Bay West Property Management
2416 Polk Street
San Francisco, CA 94109

Tel: 415.345.1270, email: clynch@bwpdm.com

Dear Mr. Lynch:

**Subject: Petrini Place, CA – SB 326 EEE Inspection Report
2001 McAllister Street, San Francisco, CA**

This report contains the results of the inspection conducted by Murphy Burr Curry, Inc. (MBC) for the Exterior Elevated Elements (EEE) inspection report for the property located at Petrini Place, 2001 McAllister Street, San Francisco, CA, and includes our recommendations for repairs. This report is in accordance with the inspection requirements described in SB 326 and California Civil Code 5551.

1. Scope of Professional Services

- 1.1.** Structural engineering services for an inspection at the subject property for the existing Exterior Elevated Elements (EEEs) which includes balconies, decks, exterior wood stairways, walkways, and railings that have a walking surface of more than six feet above ground level in accordance with SB 326 and Civil Code 5551 requirements.
- 1.2.** The number of EEEs required to be inspected is taken as a “statistically significant sample” of the total number of EEEs in accordance with SB 326. A statistically significant sample indicates sufficient elements inspected to provide 95 percent confidence that the sample’s results reflect the whole, with a margin of error of no greater than plus or minus 5 percent. The number of EEEs and the corresponding number of required and conducted inspections are as follows:

<i>EEE Type</i>	<i>Number</i>	<i>Number of Inspections Required</i>	<i>Number of Inspections Conducted</i>
Decks	90	73	90
Stairs / Walkways	20	20	20
Total	110	93	110

- 1.3.** Our professional opinion expressed in this report is limited by the following: Our inspection was visual and did not include testing. Structural framing of the decks and walkways was covered by the ceilings. All the decks were observed from the top and below. The contractor provided access to the spaces below the decks and walkways, allowing us to observe signs of water damage at the ceiling and edge of the decks. No other probes were conducted. MBC requested opening up 20 units and 3 walkway ceilings (Ref. Appendix A) to inspect the structural framing for possible water intrusion.



April 15, 2025

Project Number: 222-141

Mr. Colin Lynch
Bay West Property Management
2416 Polk Street
San Francisco, CA 94109

Tel: 415.345.1270, email: clynch@bwpm.com

Dear Mr. Lynch:

**Subject: SB 326 EEE Inspection Completion Report
Petrini Place, 2001 McAllister Street, San Francisco, CA**

At your request we performed a final Structural Observation site visit on April 15, 2025, to observe the walkway repairs completed per the recommendations in our SB 326 EEE Inspection Report for the property, dated 9/12/2023. From our observations of the walkways during this visit and of the five deck repairs during previous Structural Observation visits conducted in 2023, it is our opinion that the repairs have been completed substantially in accordance with the recommendations in the referenced SB 326 EEE Inspection Report and structural drawings for the repairs prepared by this office.

This report may not be used by any persons other than the Client without the expressed permission of Murphy Burr Curry. The conclusions are based on our site visits, visual observations of exposed and accessible materials, information supplied by the Client, and our experience in the field of structural engineering with similar buildings. Our professional opinions, conclusions, and recommendations are made in accordance with generally accepted engineering principles and practices. We have not performed a detailed analysis of the building, nor did we do any investigations to determine hidden structural or soil conditions. No tests for asbestos and/or other hazardous materials were conducted. No warranty is expressed or implied.

Thank you for working with us on this project. Please contact the undersigned if you have any questions.

Sincerely,

MURPHY BURR CURRY, INC.

A handwritten signature in blue ink that reads 'Alan Burr'.

Alan Burr, SE 5062
President



2. Description of Load-Bearing Components and Associated Waterproofing System

2.1. Exterior Stairs/Walkways Load-Bearing Components

- 2.1.1. The exterior stairs are constructed from steel stringers with precast concrete treads supported by wood-framed walkways. The stringers have hanger connections to the landing beams at the top end and are welded to the steel base plate at the bottom end. The precast treads are supported by embedded steel plates welded to steel angles, which are welded to the inside face of the steel channel stringers.
- 2.1.2. The intermediate landings consist of concrete on a metal deck supported by perimeter steel channels.
- 2.1.3. Stair stringers are typically welded to the steel plates embedded in the concrete footings.
- 2.1.4. The railings at the stairs are closely spaced steel bar balusters with intermediate posts welded to the top of the steel stringers. At the landing, the railing posts are welded to the continuous steel plate which is bolted to the wood edge beam.
- 2.1.5. More information on framing at each stair can be found in Appendix C.

2.2. Exterior Stairs Waterproofing System

- 2.2.1. The primary structural steel members of the exterior stairs are painted and are exposed to the weather. The walkway wood joists and plywood sheathing are covered on top with a concrete topping. There is a waterproofing membrane between the concrete topping and the plywood sheathing. Metal flashing is installed at the edge of the landing beams. All free sides of the walkways, and also below their framing, are wrapped by gyp boards/ceilings.
- 2.2.2. Sheet metal flashing has been installed between the open sides of the stair walkways and at the intersection of the walkways and building walls or perimeter beams.

2.3. Deck Load-Bearing Components

- 2.3.1. The decks are typically wood-framed, consisting of Pressure-Treated (P.T.) wood joists (typically 2x). The joists are hung off of a ledger beam that is through-bolted to the exterior building wall on one side and there are LVL wood beams at the front edge of the balconies. For balconies surrounded by the building walls, the LVL edge beams are supported by the wood posts inside the exterior building wall.
- 2.3.2. There are cantilevered balconies consisting of wood joists cantilevered off of the building with a rim LVL beam supporting the railing at the front and sides of the balconies.
- 2.3.3. The surface of the decks consists of sloped 2" to 1½" thick concrete topping on top of the structural plywood sheathing. The plywood spans between the 2x joists.
- 2.3.4. The railings around the decks consist of steel posts welded to the continuous steel plates which are bolted through the front and side wood beams. There are steel bar balusters welded on the top and bottom steel railing, which spans between the steel railing posts.
- 2.3.5. More information on the deck framing can be found in Appendices D & E.

2.4. Deck Waterproofing System

- 2.4.1. The wood framing joists are P.T. covered on top with $\pm 2"$ sloped concrete topping. There is a waterproofing membrane between the concrete topping and the plywood sheathing above the deck joists. Metal flashing is installed at the edge of the landing beams which are wrapped in gypsum board on the side. The deck framing is covered by furred ceiling framing for the gypsum board ceiling.
- 2.4.2. The decks are waterproofed with sheet metal flashing installed on top of the edge beams and a membrane. The sheet metal and waterproofing membrane extend down the sides of the pressure-treated edge beams.
- 2.4.3. Waterproofing material and sheet metal flashing were observed at the intersection of the decks and the exterior walls.

3. Observed Conditions and Recommended Repairs

3.1. Summary

- 3.1.1. All balconies and stairs were observed from the top and bottom. However, the structural framing was covered by the concrete topping on top and the gypsum board ceiling from below. At a selected number of balconies and stairs, openings were made to observe the structural framing members.
- 3.1.2. Photos of all significant observed damage (for the decks that were opened) are provided in Appendix D. Recommended repair measures can be found in Appendix E. Except for the damaged balconies listed in Appendix A, the observed condition of the decks was generally satisfactory.
- 3.1.3. In our opinion, the observed conditions for the damaged balconies listed in Appendix A present an immediate threat to the health and safety of the residents. MBC recommends immediate shoring at the balconies of units 246, 254, 255, 329, and 333 until repairs are completed. This is due to extensive beam damage observed at the edge beams.
- 3.1.4. Walkways water damage observed is listed in Appendix A. In our opinion, the observed conditions do not present an immediate threat to the health and safety of the residents, however, we recommend that the repairs described below be completed within the next six months.
- 3.1.5. All specifications for waterproofing shall be provided by a waterproofing specialist and/or architect. The recommendations in the following report are subject to detailed specifications by a waterproofing specialist.
- 3.1.6. Structural repair details are provided in Appendix E. Appendix A provides a detailed list of where the repairs in Appendix E are recommended. If the contractor performs the repairs in full conformance with our recommendations, we expect the remaining useful life of the load-bearing components and associated waterproofing system to extend at least until the next round of inspections in nine years, notwithstanding any hidden damages unobserved by MBC.
- 3.1.7. Additional framing damages may be found during repair work as hidden conditions are exposed. Any additional damages found should be repaired in a similar manner to that described in this report.

3.2. Exterior Stairs/Walkways

- 3.2.1. The most common observed stair damages were:

3.2.1.1. Corrosion signs at the connection between the embedded steel plates below the precast threads and the steel angle supporting the threads. Clean rusted steel in accordance with the SSPC-SP15 standard, and apply zinc-based primer and protective finish coating to the repair area.

3.2.1.2. Rusted handrails and blusters and stair stringer. Clean rusted steel in accordance with the SSPC-SP15 standard, and apply zinc-based primer and protective finish coating to the repair area.

3.2.2. The most common observed walkway damages were:

3.2.2.1. Walkway beam water damage (by unit #216). Repair details for observed damage are similar to the repair provided in Appendix E.

3.2.2.2. Concrete topping cracks greater than 1/8". Patch the existing crack with concrete to avoid further water intrusion into the structural framing below.

3.2.3. More photos of the stair/walkway damage at each building are provided in Appendix C.

3.3. *Decks*

3.3.1. In addition to the stair damage, the following damages were observed at the decks:

3.3.1.1. Water damage at LVL edge beams supporting the balcony joists.

3.3.2. Repair details for observed damages are provided in Appendix E. More photos of the deck damages at each building are provided in Appendix D.

4. *Limitations*

4.1. This report may not be used by any person or persons other than the Client without the expressed permission of Murphy Burr Curry. These preliminary findings, conclusions, and recommendations are based on a brief site visit, visual observations of exposed and accessible materials, information supplied by the Client, and our experience in the field of structural engineering with similar buildings. Our professional opinions, conclusions, and recommendations are made in accordance with generally accepted engineering principles and practices. We have not performed a detailed analysis of the building, nor did we do any investigations to determine the site's hidden structural or soil conditions. No tests for asbestos and/or other hazardous materials were conducted. No warranty is expressed or implied.

Thank you for working with us on this project. Please review this report, and contact the undersigned if you have any questions.

Regards,

MURPHY BURR CURRY, INC.

Somayeh Mirhosseini

Project Engineer

Encl.


Appendix A Stair & Balconies Opened & Site Plans

Appendix B Typical Balcony Framing Detail

Appendix C Stair & Walkways Observation

Appendix D Balcony Observation by Building & Unit

Appendix E Structural Repair Measures



Alan Burr, SE 5062

President

Pages 5

Pages 11

Pages 13

Pages 28

Pages 62

APPENDIX A

***STAIR / WALKWAYS & BALCONIES OPENED
& SITE PLANS***

Stairs & walkways observed damage (exposed):

Stairs	Damage Observed	Repair Recommendation
by Unit #201	Rusted Steel plates below concrete thread	See 3.2.1.1
by Unit #210	Rusted steel plates below concrete thread & rusted steel stringer	
by Unit #236	Rusted Steel plates below concrete thread	
by Unit #248	Rusted handrails and blusters	
by Unit #250	Rusted Steel plates below concrete thread	


Walkways	Damage Observed	Repair Recommendation
By Unit #220	Concrete topping cracks greater than 1/8".	See 3.2.2.2

Stairs & walkways observed damage (being opened per MBC's request):


Walkways (Opened)	Damage Observed	Repair Recommendation
by Unit #216	Edge beam water damage	Replace the damaged beam per Appendix E
by Elevator #2	N/A	N/A
by Unit #229	N/A	N/A
by Unit #248	N/A	N/A

Stairs & walkways observed damage (being opened per MBC's request):


Balconies (Opened)	Damage Observed	Repair Recommendation
#201	N/A	N/A
#208	N/A	N/A
#210	N/A	N/A
#212	N/A	N/A
#218	N/A	N/A
#221	N/A	N/A
#233	N/A	N/A
#246	Edge beam water damage	Replace the damaged beam per Appendix E
#248	N/A	N/A
#250	N/A	N/A
#251	N/A	N/A
#252	N/A	N/A
#254	Edge beam water damage	Replace the damaged beam per Appendix E
#255	Edge beam water damage	Replace the damaged beam per Appendix E
#308	N/A	N/A
#310	N/A	N/A
#323	N/A	N/A
#326	N/A	N/A
#329	Edge beam water damage	Replace the damaged beam per Appendix E
#333	Edge beam water damage	Replace the damaged beam per Appendix E



Second Floor Site Plan Showing The Walkways Being Locally Opened




Second Floor Site Plan With The Units Being Opened



Third Floor Site Plan With The Units Being Opened

APPENDIX B

TYPICAL BALCONY STRUCTURAL DETAIL



Typical Balcony Detail (12/S6.3 Original Construction Drawings 2001)

APPENDIX C

STAIR & WALKWAYS OBSERVATIONS

Building A



1: Stair by Unit 201




2: Stair by Unit 201



3: Stair by Unit 201



4: Stair by Unit 201




5: Stair by Unit 201



6: Stair by Unit 201

Building A



7: Stair by Unit 206




8: Stair by Unit 206




9: Stair by Unit 206



10: Stair by Unit 206



11: Stair by Unit 206



12: Stair by Unit 206


Building A



13: Stair by Unit 210



14: Stair by Unit 210



15: Stair by Unit 210



16: Stair by Unit 210



17: Stair by Unit 210



18: Stair by Unit 210

Building A



19: Stair by Elevator #3



20: Stair by Elevator #3



21: Stair by Elevator #3



22: Stair by Elevator #3



23: Stair by Elevator #3



24: Stair by Elevator #3

Building A


25: Stair by Elevator #3



26: Stair by Elevator #3 (by unit 216)



27: Stair by Elevator #3



28: Stair by Elevator #3



29: Stair by Elevator #3 (opened next to unit 218 from below)



30: Stair by Elevator #3 (opened next to unit 216 from below)

Building A



31: Stair by Unit 220




32: Stair by Unit 220



33: Stair by Unit 220



34: Stair by Unit 220



35: Stair by Unit 220



36: Stair by Unit 220

Building B



37: Stair by Unit 229



38: Stair by Unit 229



39: Stair by Unit 229



40: Stair by Unit 229



41: Stair by Unit 229



42: Stair by Unit 229

Building B



43: Stair by Unit 232



44: Stair by Unit 232



45: Stair by Unit 232



46: Stair by Unit 232



47: Stair by Unit 232



48: Stair by Unit 232

Building B

49: Stair by Unit 236



50: Stair by Unit 236



51: Stair by Unit 236



52: Stair by Unit 236



53: Stair by Unit 236



54: Stair by Unit 236

Building C



55: Stair by Unit 240



56: Stair by Unit 240



57: Stair by Unit 240



58: Stair by Unit 240



59: Stair by Unit 240



60: Stair by Unit 240

Building C



61: Stair by Unit 248



62: Stair by Unit 248



63: Stair by Unit 248



64: Stair by Unit 248



65: Stair by Unit 248



66: Stair by Unit 248

Building D

67: Stair by Unit 250



68: Stair by Unit 250



69: Stair by Unit 250



70: Stair by Unit 250



71: Stair by Unit 250



72: Stair by Unit 250

Building D



73: Stair by Unit 254




74: Stair by Unit 254




75: Stair by Unit 254



76: Stair by Unit 254



77: Stair by Unit 254



78: Stair by Unit 254

Building D



79: Stair by Unit 255



80: Stair by Unit 255



81: Stair by Unit 255



82: Stair by Unit 255

APPENDIX D

***BALCONY OBSERVATION SUMMARY
BY BUILDING & UNIT***

Building A (2ND Floor)



1: Unit 201 Balcony



2: Unit 201 Balcony



3: Unit 201 Balcony



4: Unit 201 Balcony



5: Unit 202 Balcony



6: Unit 202 Balcony



7: Unit 204 Balcony



8: Unit 204 Balcony



9: Unit 205 Balcony




10: Unit 205 Balcony



11: Unit 206 Balcony



12: Unit 206 Balcony



13: Unit 207 Balcony



14: Unit 207 Balcony



16: Unit 208 Balcony



16: Unit 208 Balcony



17: Unit 208 Balcony



18: Unit 208 Balcony



19: Unit 209 Balcony




20: Unit 209 Balcony



21: Unit 210 Balcony



22: Unit 210 Balcony



23: Unit 211 Balcony



24: Unit 211 Balcony



25: Unit 211 Balcony



26: Unit 211 Balcony



27: Unit 212 Balcony



28: Unit 212 Balcony



29: Unit 212 Balcony



30: Unit 212 Balcony



31: Unit 212 Balcony



32: Unit 212 Balcony



33: Unit 213 Balcony



34: Unit 213 Balcony



35: Unit 215 Balcony



36: Unit 215 Balcony



37: Unit 218 Balcony



38: Unit 218 Balcony



39: Unit 218 Balcony



40: Unit 218 Balcony



41: Unit 218 Balcony



42: Unit 218 Balcony



43: Unit 220 Balcony



44: Unit 220 Balcony



45: Unit 220 Balcony



46: Unit 220 Balcony



47: Unit 220 Balcony



48: Unit 220 Balcony



49: Unit 221 Balcony



50: Unit 221 Balcony



51: Unit 221 Balcony



52: Unit 221 Balcony



53: Unit 221 Balcony



54: Unit 221 Balcony

Building B (2ND Floor)




55: Unit 222 Balcony



56: Unit 222 Balcony



57: Unit 223 Balcony



58: Unit 223 Balcony



59: Unit 224 Balcony



60: Unit 224 Balcony



61: Unit 225 Balcony



62: Unit 225 Balcony



63: Unit 226 Balcony



64: Unit 226 Balcony



65: Unit 227 Balcony




66: Unit 227 Balcony



67: Unit 228 Balcony



68: Unit 228 Balcony



69: Unit 229 Balcony



70: Unit 229 Balcony



71: Unit 230 Balcony



72: Unit 230 Balcony



73: Unit 231 Balcony



74: Unit 231 Balcony



75: Unit 232 Balcony



76: Unit 232 Balcony



77: Unit 233 Balcony



78: Unit 233 Balcony



79: Unit 233 Balcony



80: Unit 233 Balcony



81: Unit 234 Balcony



82: Unit 234 Balcony

Building C (2ND Floor)



83: Unit 237 Balcony



84: Unit 237 Balcony



85: Unit 238 Balcony



86: Unit 238 Balcony



87: Unit 239 Balcony



88: Unit 239 Balcony




89: Unit 240 Balcony



90: Unit 240 Balcony



91: Unit 241 Balcony



92: Unit 241 Balcony



93: Unit 242 Balcony



94: Unit 242 Balcony



95: Unit 243 Balcony



96: Unit 243 Balcony



97: Unit 244 Balcony



98: Unit 244 Balcony



99: Unit 245 Balcony



100: Unit 245 Balcony



101: Unit 246 Balcony



102: Unit 246 Balcony



103: Unit 246 Balcony



104: Unit 246 Balcony



105: Unit 248 Balcony



106: Unit 248 Balcony



107: Unit 248 Balcony



108: Unit 248 Balcony

Building D (2ND Floor)



109: Unit 250 Balcony



110: Unit 250 Balcony



111: Unit 250 Balcony



112: Unit 250 Balcony



113: Unit 251 Balcony



114: Unit 251 Balcony



115: Unit 251 Balcony



116: Unit 251 Balcony



117: Unit 252 Balcony



118: Unit 252 Balcony



119: Unit 252 Balcony



120: Unit 252 Balcony



121: Unit 253 Balcony



122: Unit 252 Balcony



123: Unit 254 Balcony



124: Unit 254 Balcony




125: Unit 254 Balcony



126: Unit 254 Balcony



127: Unit 255 Balcony



128: Unit 255 Balcony



129: Unit 255 Balcony



130: Unit 255 Balcony

Building A (3RD Floor)



131: Unit 308 Balcony



132: Unit 308 Balcony



133: Unit 308 Balcony



134: Unit 308 Balcony




135: Unit 308 Balcony



136: Unit 308 Balcony



137: Unit 309 Balcony




138: Unit 309 Balcony



139: Unit 309 Balcony



140: Unit 309 Balcony



141: Unit 310 Balcony



142: Unit 310 Balcony



143: Unit 310 Balcony



144: Unit 310 Balcony



145: Unit 311 Balcony



146: Unit 311 Balcony



147: Unit 312 Balcony



148: Unit 312 Balcony




149: Unit 313 Balcony



150: Unit 313 Balcony



151: Unit 315 Balcony



152: Unit 315 Balcony



153: Unit 318 Balcony



154: Unit 318 Balcony



155: Unit 320 Balcony



156: Unit 320 Balcony



157: Unit 321 Balcony



158: Unit 321 Balcony

Building B (3RD Floor)

159: Unit 322 Balcony



160: Unit 322 Balcony



161: Unit 323 Balcony



162: Unit 323 Balcony



163: Unit 323 Balcony



164: Unit 323 Balcony



165: Unit 324 Balcony



166: Unit 324 Balcony



167: Unit 325 Balcony



168: Unit 325 Balcony



169: Unit 326 Balcony



170: Unit 326 Balcony



171: Unit 326 Balcony



172: Unit 326 Balcony



173: Unit 327 Balcony



174: Unit 327 Balcony



175: Unit 328 Balcony



176: Unit 328 Balcony



177: Unit 329 Balcony



178: Unit 329 Balcony



179: Unit 329 Balcony



180: Unit 329 Balcony



181: Unit 330 Balcony



182: Unit 330 Balcony



183: Unit 331 Balcony



184: Unit 331 Balcony



185: Unit 332 Balcony



186: Unit 332 Balcony



187: Unit 333 Balcony



188: Unit 333 Balcony




189: Unit 334 Balcony




190: Unit 334 Balcony


APPENDIX E
STRUCTURAL REPAIR MEASURES




Typical Balcony Partial Plan at All Units Except #254 & #255




Section 3/S3.246 (Typical Deck Repair)




Section 4/S3.246 (Typical Deck Repair)



Typical Balcony Partial Plan at Units #254 & # 255



Section 3/S3.254 (Typical Deck Repair)



Section 4/S3.254 (Typical Deck Repair)